

PHENIX WEEKLY PLANNING



12/02/2010 Don Lynch



2010 Shutdown (Overview)

Start Date End Date

| Design, Eng'g, fabrication, procurement and site preparation tasks in support of shutdown tasks | Done | Done |
|---|-------------|-------|
| Shutdown Startup Tasks | Done | Done |
| Gas system maintenance, repair and upgrade | In progress | 12/24 |
| PHENIX Infrastructure maintenance, repair and upgrade | In Progress | 12/24 |
| Remove RPC Prototypes | Done | Done |
| Remove HBD | Done | Done |
| Remove RXNP | Done | Done |
| Remove/Reinstall BBC | Done | Done |
| Remove Re-install MPC | In Progress | 12/3 |
| RPC3N & MuTrigger unfinished business | Done | Done |
| Remove current BP, install new BP | Done | Done |
| DC/PC maintenance and repair (mid summer) | Done | Done |
| Install RPC35 (including Absorbers) | Done | Done |
| MuTr maintenance, repair and upgrade | In Progress | 12/24 |
| Install VTX | In Progress | 12/9 |



TECHNICAL NUPPORT

This Week:

Survey MMS, CM and beampipe

Re-install BBC's and MPC's

Survey of VTX West

Continue VTX Cabling and Piping

Complete RPC35 services

Install VTX East

Install VTX Services

Continue restoring services to CM and MMS

Future upgrades support



Next Week

Complete VTX Installation

Begin End of shutdown tasks


Complete restoring services to CM and MMS

Final VTX Survey

Install RPC1 Prototype and Prototype PE & Pb Absorbers

Roll -in EC

Future upgrades support





TECHNICAL NUPPORT 10-0




























12/02/2010
























12/02/2010




TECHNICAL SUPPORT 20-0



Borated Poly Absorbers, (Lead Absorbers are below, not seen in picture)

Prototype Absorbers go here




RPC1 Prototype Goes Here

12/02/2010


Installation scheme for Borated Poly and lead prototypes:

Installation support structure attached to CM

Prototype absorbers lifted with crane, attached to installation support structure by trolley and slid into position



Shelf support to help align and position absorber prototypes.



12/02/2010



TECHNICAL NUPPORT 20-0

Remaining Shutdown Tasks

| Project | <u>Task</u> | Completion Date | Task Duration | Personnel reqmts | <u>Notes</u> |
|---------|--|--------------------|---------------|------------------|--------------|
| PHENIX | Chiller cooling water | Done | | | Done |
| VTX | Assemble west 1/2 detector | Done | | | Done |
| VTX | Design survey theodolite support brackets for CM lead shield | Done | | | Done |
| VTX | Route fibers rack room to CME Rack | Done | | | Done |
| PHENIX | Bakeout/activate NEG for new BP | Done | | | Done |
| PHENIX | Leak check new BP | Done | | | Done |
| VTX | Test west 1/2 detector | Done | | | Done |
| VTX | Survey east barrels 1-4 | Done | | | Done |
| PHENIX | Re-run MuTriggger fiber from MMS to rack room | Done | | | Done |
| VTX | Fabricate survey support brackets | Done | | | Done |
| VTX | Bring Support structure to Chem Lab - Done | Done | | | Done |
| VTX | Install survey support brackets | Done | | | Done |




| <u>Project</u> | <u>Task</u> | <u>Completion</u> <u>Date</u> | Task Duration | <u>Personnel reamts</u> | Notes |
|----------------|---|----------------------------------|---------------|-------------------------|-------|
| RPC3S | Build TVB wall | Done | | | Done |
| VTX | Survey west 1/2 detector | Done | | | Done |
| VTX | Re-install bridge water manifold and cable trays | Done | | | Done |
| VTX | Chiller platform 480V power | Done | | | Done |
| VTX | Assemble east 1/2 detector | Done | | | Done |
| PHENIX | Re-install MuTr station 2 channel air distribution | Done | | | Done |
| VTX | Prepare thermocouple map | Done | | | Done |
| VTX | Test east 1/2 detector | Done | | | Done |
| VTX | Install NOVEC piping from chiller platform area to VTX area | Done | | | Done |
| VTX | Receive extension rails/design/modify for installation | Done | | | Done |
| VTX | Survey east 1/2 detector | Done | | | Done |
| PHENIX | Install access to inside MMS | Done | | | Done |



| T |
|----------|
| Ė |
| EC |
| H |
| H |
| N |
| tc |
| 7 |
| Ā |
| A |
| |
| |
| > |
| u |
| Sup |
| P |
| ' |
| ORT |
| |
| T |
| |
| 7 |
| 0 |
| 1 |
| 0 |
| |

| <u>Project</u> | <u>Task</u> | <u>Completion</u> <u>Date</u> | Task Duration | <u>Personnel reamts</u> | <u>Notes</u> |
|----------------|--|----------------------------------|---------------|-------------------------|--------------|
| VTX | Mate east and west 1/2 detectors | Done | | | Done |
| VTX | Survey/align east and west detector | Done | | | Done |
| VTX | Modify strongbacks for basket lift | Done | | | Done |
| VTX | Install extension rails | Done | | | Done |
| PHENIX | Veterans Day Holiday | Done | | | Done |
| RPC3S | NRTL cable trays | Done | | | Done |
| VTX | Transport west 1/2 detector to IR | Done | | | Done |
| VTX | Install west 1/2 detector | Done | | | Done |
| VTX | Assemble and install NOVEC distribution manifolds near VTX | Done | | | Done |
| RPC3S | Re-install shielding | Done | | | Done |
| VTX | Install humidity sensors | Done | | | Done |
| PHENIX | Remove bakeout equipment | Done | | | Done |
| PHENIX | Survey and align MMS, CM and new BP | Done | | | Done |



| <u>Project</u> | <u>Task</u> | <u>Completion</u> <u>Date</u> | Task Duration | Personnel reqmts | <u>Notes</u> |
|-------------------|--|----------------------------------|---------------|------------------|--------------|
| PHENIX | Annual PHENIX Safety Review | Done | | | Done |
| PHENIX | Install power upgrade to bridge | Done | | | Done |
| RPC3S | Finalize cable tray/Cable installation | Done | | | Done |
| RPC3S | Final piping | Done | | | Done |
| VTX | Install west 1/2 detector Bias, LV and signal cables | Done | | | Done |
| VTX | Install one Chiller for QA testing (on ground) | Done | | | Done |
| VTX | Connect west 1/2 detector to NOVEC cooling | Done | | | Done |
| VTX | Survey/align west 1/2 detector | Done | | | Done |
| VTX | Transport east 1/2 detector to IR | Done | | | Done |
| RPC1&Abs Proto | Installation plan | Done | | | Done |
| RPC1&Abs Proto | WP | Done | | | Done |
| PHENIX | Re-install BBCs cabling/cooling pipes | Done | | | Done |
| PHENIX | Re-install BBCs | Done | | | Done |
| PHENIX | AH South exit chiller platform installation | Done | | | Done |
| VTX | Install 3 chillers on chiller platform | Done | | | Done |



| T | , <u>Project</u> | <u>Task</u> | <u>Completion</u> <u>Date</u> | Task Duration | Personnel regmts | Notes |
|-----|-------------------|---|----------------------------------|---------------|---|-------------------------|
| E | VTX | Install east 1/2 detector | Done | | | Done |
| H | VTX | Route 100 LV cables from bridge rack to near VTX | Done | | | Done |
| 7 | , VTX | Route 260 duplex/simplex fibers from CME rack to near VTX | Done | | | Done |
| C | VTX | Route 7 Belden 16 pair cable trunks from CME rack to near the VTX | Done | | | Done |
| 2 | PHENIX | Install East Vertical Lampshade on MMS | Done | | | Done |
| SU | VTX | Survey/align east 1/2 detector | 12/2/2010 | 1 day | PHENIX tech, designer, 2 surveyors | after installation |
| P | RPC3S | Thermostats | 12/3/2010 | 1 day | 1 electrician | As convenient |
| Po | RPC1&Abs Proto | Installation fixtures design and fabrication | 12/3/2010 | 3 days | PHENIX ME, Designer | In Progress |
| RT | VTX | Install interlock PLC on bridge | 12/3/2010 | 2 weeks | PHENIX EE, electrician, 1 PHENIX Tech | As soon as PLC is ready |
| 20 | VTX | Route 100+ thermocouple extensions from PLC box to near VTX | 12/3/2010 | 1 day | 3 PHENIX techs | In Progress |
| 010 | RPC3S | Re-install FCAL and any other disrupted subsystems | 12/3/2010 | 2 days | 2 PHENIX techs, 1 PHENIX EE | As convenient |
| | VTX | Install east 1/2 detector Bias, LV and signal cables | 12/3/2010 | 1 week | 2 PHENIX techs | after survey |
| | PHENIX | WP for DC repairs | 12/3/2010 | 2 days | ME | As convenient |



| O-ON TROADEN TYCHOM | + |
|---------------------|----|
| HAODAN NACHORF | |
| THOAL NATHORF | |
| THOAL NATHORF | H |
| AN NUPPORT | N |
| AN NUPPORT | # |
| HAOADEN | |
| HAOADEN | A |
| ORT | |
| ORT | S |
| ORT | u |
| ORT | P |
| | P |
| | 00 |
| | 17 |
| 20-0 | |
| 0-0 | 2 |
| 0 | 0 |
| | 0 |
| | |

| <u>Project</u> | Task | <u>Completion</u> <u>Date</u> | Task Duration | <u>Personnel reamts</u> | <u>Notes</u> |
|----------------|---|----------------------------------|---------------|--|---|
| PHENIX | Re-install MPCs | 12/3/2010 | 1 week | 2 PHENIX techs | In Progress |
| VTX | Connect east 1/2 detector to NOVEC cooling | 12/3/2010 | 2 days | 2 PHENIX techs | Immediately after survey |
| VTX | In situ QA electronics test on east 1/2 detector | 12/3/2010 | 2 days | PHENIX scientists A/R | As services are installed |
| VTX | Final VTX survey | 12/3/2010 | 1 day | 1 PHENIX tech, designer, 2 surveyors | After east QA |
| VTX | Final BP survey | 12/3/2010 | 1 day | 1 PHENIX tech, designer, 2 surveyors | After east QA |
| PHENIX | Install MuID collars | 12/6/2010 | 1 day | 3 PHENIX techs | After EC in IR |
| PHENIX | Re-attach cables, gas piping, water piping and fibers to CM and MMS | 12/7/2010 | 2 weeks | 3 PHENIX techs | In Progress |
| PHENIX | MuTr and MuTrigger remaining subsystem tasks and tests | 12/7/2010 | 2 weeks | 1 PHENIX techs MuTr/Trig Groups | As convenient |
| PHENIX | Remove manlifts, decking and 12 ton crane from IR to run storage | 12/8/2010 | 1 day | 3 PHENIX techs | After BBCs & MPCs & VTX installed |
| PHENIX | Move MuID collars to IR | 12/8/2010 | 1 day | 3 PHENIX techs | After BBCsMPCs |
| PHENIX | Prep EC for move to IR | 12/8/2010 | 1 day | 3 PHENIX techs | After BBCs & MPCs & VTX |
| PHENIX | Move EC to IR | 12/9/2010 | 1 day | 3 PHENIX techs | After Prep |



| T | <u>Project</u> | <u>Task</u> | <u>Completion</u> <u>Date</u> | Task Duration | Personnel reqmts | <u>Notes</u> |
|--------|----------------|--|----------------------------------|---------------|--|--|
| C | PHENIX | Design CM alignment stops | 12/10/2010 | 1 week | ME, designer | As time permits |
| H | PHENIX | Fabricate CM alignment stops | 12/10/2010 | 1 week | CS | After design |
| N | PHENIX | Close access to MMN | 12/10/2010 | 1 day | 1 PHENIX tech | > MuTr/ Trig < flam gas |
| t C | RPC35 | RPC gas controllers final installation and RPC subsystem commissioning | 12/10/2010 | 1 week | 1 PHENIX tech, RPC Group | As soon as convenient |
| A | PHENIX | Wire dumb waiter | 12/10/2010 | 1 day | Electrician | After dumb waiter installed |
| SU | PHENIX | Fold down EC platforms and install dumb waiter | 12/10/2010 | 1 day | 2 carpenters, 2 riggers | After EC in IR |
| PP | PHENIX | Re-install EC cables, fibers, water and gas piping | 12/10/2010 | 4 days | 3 PHENIX techs, 2 scientists, 1 electrican | After EC in IR |
| 02 | PHENIX | DC repairs | 12/15/2010 | 3 days | 1 PHENIX tech, PHENIX scientists A/R | After EC cables, etc. installed |
| し | PHENIX | Gas mixing house R-134A shed addition R134A bottle warmers | 12/15/2010 | 1 day | 1 PHENIX Tech | Get CAD approval then order. Install when convenient |
| 10 | PHENIX | Pink sheets, blue sheets, white sheets | 12/24/2010 | 2 weeks | 2 PHENIX techs, PHENIX scientists A/R | After DC Repairs |
| | PHENIX | Chiller platform fire detection and suppression | 12/24/2010 | 1 week | 1 CAD plumbers, 1electrican | ASAP after platform is installed |



| <u>Project</u> | <u>Task</u> | <u>Completion</u> <u>Date</u> | Task Duration | Personnel reamts | Notes |
|-------------------|--|----------------------------------|---------------|------------------|-----------------------------|
| PHENIX | Assemble shield wall | 12/24/2010 | 4 days | 1 rigging crew | After EC rolled |
| PHENIX | Start flammable gas | 12/24/2010 | 1 day | 1 PHENIX tech | After shield w |
| FoCal Proto | Design plan | 12/30/2010 | 2 weeks | PHENIX ME | In Progress |
| FoCal Proto | Installation plan | 12/30/2010 | 2 weeks | PHENIX ME | In Progress |
| PHENIX | Install plug door | 12/30/2010 | 1 day | 1 rigging crew | After shield w built |
| PHENIX | Close shield wall | 12/30/2010 | 1 day | 3 PHENIX techs | After pink/blue/whit sheets |
| PHENIX | Install safety interlocks | 12/30/2010 | 1 day | CAD safety | After shield w |
| PHENIX | Close out all 2010 shutdown WP's | 12/31/2010 | 1 day | 1 PHENIX ME | After shutdow completed |
| RPC1&Abs Proto | Electronics & Gas Support Installation | 12/31/2011 | 3 days | 3 PHENIX techs | If Time Permit |
| PHENIX | End of shutdown party | 1/7/2011 | 1 day | All of PHENIX | After shutdow completed |



| T | |
|----------|---|
| Ė | Γ |
| HOHOL | L |
| H | |
| Ñ | |
| 7 | |
| * | |
| A | |
| TCAL | |
| L | |
| S | |
| ũ | |
| P | |
| NUPP | |
| 6 | |
| ORT | L |
| 7 | |
| ı | |
| 2 | |
| 20 | |
| 10 | |
| 0 | |

| Project | <u>Task</u> | Completion Date | Task Duration | Personnel reqmts | Notes |
|-------------------|--|--------------------|---------------|------------------------|-----------------|
| RPC1&Abs Proto | Installation | 12/8/2010 | 3 days | 3 PHENIX techs | If Time Permits |
| FoCal Proto | ESRC review | >1/1/2011??? | 2 weeks | PHENIX ME | Not Scheduled |
| FoCal Proto | Support structure design | >1/1/2011??? | 3 days | PHENIX ME, Designer | Not Scheduled |
| FoCal Proto | Support structure fabrication | >1/1/2011??? | 2 weeks | 2 PHENIX techs, CS | Not Scheduled |
| FoCal Proto | Electronics, cooling, gas support design | >1/1/2011??? | 3 days | PHENIX ME, Designer | Not Scheduled |
| FoCal Proto | Electronics, cooling, gas support fabrication | >1/1/2011??? | 1 week | 2 phenix TECHS | Not Scheduled |
| FoCal Proto | Electronics, cooling, gas support installation | >1/1/2011??? | 3 DAYS | 3 phenix TECHS | Not Scheduled |
| FoCal Proto | Support structure installation | >1/1/2011??? | 2 DAYS | 3 phenix TECHS | Not Scheduled |



TECHNICAL SUPPORT

2010

2010 Building Maintenance Issues

- Roof leaks in utility bathroom at northwest corner behind tech offices, over door between rack room and assembly hall and over door between control room and elect. ass'y room.
- General maintenance for Trailer Offices (in progress)
- Roof leaks in laser room and IR (southeast corner)
- Flooding in AH/ Driveway heaving [Lake PHENIX]
- New HVAC in Control Room and Conference Room









PHENIX Procedure Review Current Status:

148 Procedures Identified

85 Made Inactive (not currently in use, will require revision to re- activate if and when necessary, available for reference purposes)



Web retrieval of latest procedures now available from PHENIX Internal:

http://www.phenix.bnl.gov/WWW/INTEGRATION/ME&Integration/DRL_procedures.htm



Safety, Security, Etc.

TECHNICAL NUPPORT 20-0

- 1. Annual PHENIX Safety review: no significant problems, waiting for minutes/action items
- 2. RPC1 Prototype & Borated Poly/Lead Absorber Review
 Detector and absorber info and installation plan sent to Y Makdisi & CAD
 Safety.
- Focal Prototype Review: Not enough info yet.

 Meeting w/ Ed K. on Monday
- 4. BNL Standards for Ethics Required Training Due by 12/31
- 5. From Ray Karol: Do Not Park Near Fire Hydrants
- 6. In preparation for the next run: get ODH training up to date: ODH-1 web course, ODH-1 practical training up-to-date, current physical. check POM calibrations, documented monthly escape pack inspections per C-A-OPM 13.26, rev 01.



Where To Find PHENIX Engineering Info



We're coming down the home stretch for the 2010 Shutdown.



Jets vs Patriots
On Monday Night!

Links for the weekly planning meeting slides, archives of past meeting slides, long term planning, pictures, videos and other technical info can be found on the PHENIX Engineering web site:

http://www.phenix.bnl.gov/WWW/INTEGRATION/ME&Integration/DRL_SSint-page.htm